## Daily Coordination Meeting








## **Daily Coordination Meeting**

#### **General Topics:**

• First full week back- keep your head in the game.




















**HOFFMAN CONSTRUCTION COMPANY** 




#### UTILITY LEVEL MOD1



Pre-mold Rem dismantle Should be uninstall BELFOR Mold remediation ELRAM Drywall install MEP+Elctrical Ready for re-install













#### SUT 38.1 LEVEL









SUT 38.2 LEVEL



#### SUBFAB BUILDOUT MOD 1






Sunday OCT 20<sup>th</sup> CRC AAe & TTNE Upper Dock.

- Temp stairs Access blocked.
- Stairs1 Access blocked, SF level only.


### SUBFAB CRC TOPCOAT




#### **BCT Pressure Test Exclusion Zone**

# Cancelled for the upcoming days. Lack of gear.


#### SUBFAB BUILDOUT MOD 2
















#### **Clean Room Wall Of Shame**




## Sami- najami







													-	-																						1		Si	ding -	East	FAB -	PSSS	
																																	B	OWD	OWN	N 30%	6						
CA	BL	BK			BG	Contract (19)	BE	BD	B	c E		BA	AZ	AY	AX	AW		v	AU	AT	AS	AR		2	P		АМ	AL	AK	/		NH .	AG	AF	AE	AD			AB A	-	The second second	вт	-
	751775		-	41/742			317732				721772			11	71171				551/5				541/542	1	-		1/532	11.			5217522	1		11.0	511751				1/502	-	9017902	-	
24	12	24 12	24	24	24 12	24 12	2		24 12	24	24	24	24		18	24	24	24	24	*********	4	24	24	24	24	24	24	24	4	17	17		24	24	ers and a start	24	24 24	24	24	28	28 28	28	Total
50%			50%		50%	50%	50		50%	58%	58%					28%	33%	28%	23%		1	71%	71%	71%	71%	71%				100%	100%	100%	1003	100	1	10%	100%		100%	100%		75%	*
																																	-									0	
0	0	0	0	0	0	0		0	0	0	Ő	0	0		0	0	0	0	0			0	0	0	0	0	0			1			1			1.		1		1.1		0	SRA
0	0	0	0	0	0	0		0	0	0	0	0	0		0	0	0	0	0	0		0	0	0	0	0 0 0 0	0	0													1	0	-
0	0	0	0	0	0	0	0	0	0	0	0	0	0		0	0	0	0	0		2	0	0	0	0	0	0									1						0	
0		0	0	0	Ŭ.	0		0	0	0	0		0		1	0	0	0	0	0	0	0	0	0	0	0	0	0		1		1	1	-		1	1	1		1	1	1	4DA
0	0	0	0	0	0	0	0	0	0	0	0				1	0	0	0	0		· · · · ·			1						1						1		1		-			•
	0		0			0		0	0	0	0				1	0	0	0			·															1							
0	0	0	0	0	0	Ó	0	0	0	1	1		1000		1	0	1	0	0			1	1		a raine	1	100	10 00 000	· · · · · · · · · · · · · · · · · · ·	1	1	1	1			1	1	- 11 T	-	1	1	1	3FK
		1						1		1					1	0	0	0			2			1												1		1					
				····	1			1							1	0	0	0	0			1	1	1								1		1		1				1		1	
	1	1-1-1-1	1.			1.1.1		1	1						1	0	0	0	0			1	1	1	1		1			1	1		1			1	1			1	1		3FA
									1	1								1				1			1												1						-
								1													-H																						
									1	1					1	1		1.1.1																		1							2
							-	1			1	-	111					1				+	1										1			1					-		Sub Fab
																			-		10.00																			1	1	1	Sub Fab
																																									1	0	
																																									9 000 LAN	0	
																																								_			
	2.00	West w	4					10.0	2 - 22 -	-			1.22	P	SSS	1			1		127		5 10	AF 10			9 - 19	24 A.		12	126			100	11 20			- 20 - V					
6	6	6	6	6	6	6	6	6	6	6	6	6	6		6	6	6	6	6			6	6	6	6	6	6	6		6	6	6	6	6		6	6	6	6				
6 100%		6	6 100%	100%	6	6		6	6	6 100%	100%	6 100%	100		6	6	6	6	6 1003			6 1003	6	6	6 100%	6 100%	6			6 100%	6	6	6			6	6 100%	6	6 100%				
1	1 100%	1	1	1 1	100%	1002	10	1	1004	1	1	1003	100	. ,	1	1 0	1	1	100.	10		1	1	1004	1	1	1003	100		1	1004	1	1	100	R	1	1	1	1002				
								1							1							1														1							
									1	1.1					1.		i i i								1.11												. 1						
						· · · · · · · · ·		1			-								- Partie			- forman	1.																				UL


				est FAB - JYG BLOWDOWN 30%																																				
TA	TE		то	AA	AB	AO	AD	AE	AF	AG	A	н	AJ	AK	AL	AM	AN	AP	A	a 1	w.	AS A	4	U I	AV	AW I	AX	AY	A2	BA	88	BC	8D	86 1	r	a	вн	BJ	вк	BL
		1001 / 100	2	601	/ 602		12 12	611 / 612	201100		6	21/622	1942		e	531/632	140			641/642	10		651/652			811	812	-		821/822			83	1/832			84	1/842		851/8
	28	28	28	15	18	31	31	31	1	31	31	31	31	31	30	31		31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	3
·	10	16		15	19	21				21	21	21	34	71	29	20		26	25	24	19	6	6	10	14	14	. 14	14	м			14	14		54	14				14
	46%	57×	39%	1002	100%	1102	1002	: 100	102 11	002	100%	100%	1102	1002	97%	900	٤	84%	\$102	77%	612	19%	192	42%	45%	45%	45%	45%	45%	19%	192	45%	45%	45%	45%	45%	19%	19%	19%	45%
17		0	0					a series		1		1	Contraction of the local distribution of the			0		0					0		0										· · · · · · · · ·			***		
		0	0			1		-		1						0		0		0	0	0	0	0	0	0	9	0	9	0	0	0	0			0	0	*	0	0
11		0																0		0	0	0	0		0	0			0	0	0		0		*		0		0	
		0		-														2			0	0	0			0														
		0	9										1			1		1			0	0	0			0	9	0	9	0	9	0			9		0		0	
	0	0	0	1. 1. 1. 19			+														0	0	0			0		····					0		····	····			0	
	0	0	0		nl					1											0	0	0		0	0	9		0	0	0	0	0		0		0		0	0
·	0 0 0	0			nk																0	0	0		0	0	0						····· *				0		0	
	*																						0																	
1										1										1		0		*			0			0	0							·····		
			0													1							0				0			0	0						0			
		i i						1		1			i i		1			i			1	0	0		1	1 1		i i	1	0	0				1 i l	1	0		0	
+																		+				0 6	0														0		0	
1.		1			1.1		1			1		1.1	1		1			1		1.1.1	111	0	0							0	0						0		0	1
-									anan <mark>a a</mark>	. hannan																and an france							•••••				0			
		1.1.								1								1		1		0 0 0 0															0			
+		1					1	1													// Destar		0				1.1.1			0	0		NAME OF TAXABLE PARTY.				0 1	ALC: NO.	0	
1		ļ								1								1																	1					
H	and see the		and the second second	State State State	-		·••••••••											-																			- and a			-
					L				an an an	han								anna			a la la								manne						dan tank				mondan	








## PSSS.1










## WJG 01J, 02J LIFT 2 & 3








## WJG 03J, 04J, 05J LIFT 2 & 3








## Walk Path Reroute WW43 & WW44








## AH104-22-00 Set - 29/10







## WJG UTILITY LEVEL BUILD OUT






**HOFFMAN CONSTRUCTION COMPANY** 



#### CUB 1








## CUB 1 – EXTERIOR/ROOF



**HOFFMAN CONSTRUCTION COMPANY** 




### CUB 2








## CUB 2 – EXTERIOR/ROOF








## CUB 2 – Crane Logistics







## CUB 2 – Crane Logistics




#### HOFFMAN CONSTRUCTION COMPANY





HOFFMAN CONSTRUCTION COMPANY









## Daily Coordination Meeting

Site Logistics North







# Daily Coordination Meeting

Site Logistics South





ALL INJURIES ARE PREVENTABLE | PEOPLE ARE THE SOLUTION | SUCCESS IS THE PRESENCE OF SAFETY

DATE/TIME OF INCIDENT: 10/09/2024, 10:45am LOCATION Utility AU/19

2024

#### WHAT HAPPENED?

A cable lug was left/placed on the bussing and shorted to ground when the transformer was being energized, thereby causing an arc flash incident.

#### **ROOT CAUSE**

Procedures / Procedure Did Not Identify Error

#### WHAT CAN THE PROJECT LEARN FROM THIS INCIDENT?

Contractor needs to take the time to go through the entire piece of gear to look for any foreign object that may have been left inside the transformer. Inspection teams have been created to audit this equipment prior to start up.

#### WHAT CORRECTIVE ACTIONS ARE BEING TAKEN?

- Team of 4 will inspect IPC transformers prior to startups and follow the inspection checklist.
- Cameras are being used to inspect smaller areas that are blocked off or are hard to view.
- Inspections and startups will be back-to-back to avoid potential tampering of the gear.
- "Swiffers" will be used to clean smaller areas for dust and debris.
- A transformer that is not connected to a power source, will be used to train the inspection teams in proper inspection methods and documentation.
- An IPC Transformer Inspection Checklist has been developed to guide the inspection teams through a thorough pre-startup audit of the equipment.





ALL INJURIES ARE PREVENTABLE | PEOPLE ARE THE SOLUTION | SUCCESS IS THE PRESENCE OF SAFETY

DATE/TIME OF INCIDENT: 10/21/2024 at 10:30 AM

LOCATION Fab 52.1 North Tool Tower Level 2

PROJECTEAGL

#### WHAT HAPPENED?

Test crew was conducting an 8hr 170 psi pressure test on a 3" UN2 PressLok Line. The crew initially pressurized the line to 20 psi and closed the valve to verify the line was holding pressure. As they continually added 20 psi, the UN2 line held through 60 psi. When the crew went to add another 20 psi, they opened the valve. Approximately 60 seconds later the 3" UN2 line blew apart at the 90 that had been pressed.

#### **ROOT CAUSE**


Management / Oversight Inadequate

#### WHAT CAN THE PROJECT LEARN FROM THIS INCIDENT?

Journeymen teaching apprentices need to have knowledge in the task at hand. When it is noticed that tools/material are missing to complete a job, the crew needs to STOP work and escalate to their Foreman.

#### WHAT CORRECTIVE ACTIONS ARE BEING TAKEN?

- Always verify employees are trained in the task they are required to oversee/complete.
- Follow new "Pre-task Plan PressLok Insert Guide" to include using insertion gauge.
- STOP work if the proper tools/equipment are not readily available and escalate concerns to Foreman.



## Daily Coordination Meeting

