





# HOFF AN Sparrow =

## Room Ready

#### **BCR & SCR Operational Readiness Tracker**


		en operational negatives			CSA & MEP
	Marin Carlo	Elram start	clean start	small wires start	
~	AC/AD	10-נוב	-17 מב	20-נוב	
East	SCR-LC211D AM/AN	-17	-24	-01 דצמ	
	SCR-LC211F AU/AV	-24	-01 דצמ	-08 דצמ	
	SCR-LC211H BB/BC	-24	-01 דצמ	-08 דצמ	
	SCR-LC211K BJ/BK				
_					
West	BCR-LC211A AC/AD				
	SCR-LC211C AM/AN	-17	-24	-01 דצמ	
	SCR-LC211E AU/AV	-24	-01 דצמ	-08 דצמ	
	SCR-LC211G BB/BC	-01 דצמ	-08 דצמ	דצמ-15	
	SCR-LC211G BB/BC	-01 דצמ	-08 דצמ	דצמ-15	
		Task Obstructed or not Open			
		Task Possible/Open/Infrastructure Present			
	%	In Progress			
		Done			

#### BCR 1E BCR 1W

Starting to Close and change locks for cleaning beginning on 20th of November








BELFOR
Mold Remediation
SCR 2W
SCR 2E
Turnover today

ELRAM Drywall install MEP+Elctrical
(AFCON,Bynet,
AfconCtrl,Megason,
Chemo ahron..)
Ready for re-install

<u>WW</u> RHS for roll-up doors













#### SUT 38.1 LEVEL









#### SUT 38.2 LEVEL




### SUBFAB BUILDOUT MOD 1




# **SUBFAB CRC TOPCOAT**




# **BCT Pressure Test Today**



## **BCT Pressure Test Tomorrow**




### SUBFAB BUILDOUT MOD 2



























#### Clean Room Wall Of Shame

Tzur-esh

Elram/TMT























PSSS.1




# PSSS.2




TC3
Dismantle
14/11
(Nights)




# **PSSS Vehicular Access**




















# WJG UTILITY LEVEL BUILD OUT








# CUB 1- Start up logisitics












# CUB 2- Load in and H&T

































# Daily Coordination Meeting





# Daily Coordination Meeting

**Site Logistics** 

South







## **Open CORs by Subcontractor**

WW 46 - 575 CORs

WW 47 – 606 CORs









# **Pinch Points**

- We are seeing another increase on the project for pinch point injuries- body parts being injured between two objects.
- These are still trending the most with hand injuries, but we did see a significant incident on Thursday with a person driving an MEWP that hit the top of the door frame they were driving through and then fell backwards and became caught between the frame and the MEWP.
- We need to reinvest our focus on area assessments and work planning to address line of fire or pinch point or danger zone hazards. For all activities our workers should be planning to protect themselves from having their body parts smashed, hit, or stuck between 2 objects.
- Body positioning is often key, but it takes identifying the pinch point ahead of being exposed to it to ensure we are in the proper position.

