Daily Coordination Meeting







Daily Coordination Meeting

General Topics:


*Avi cranes shutdown tomorrow

• No night shift Thur 07 Nov jobsite closes at 17:00, jobsite reopens 06:30 Fri 08 Nov






UTILITY LEVEL MOD1



Pre-mold Rem dismantle
Should be uninstallBELFOR
Mold remediationELRAM
Drywall installMEP+Elctrical
Ready for re-install












SUT 38.1 LEVEL









SUT 38.2 LEVEL




SUBFAB BUILDOUT MOD 1



SUBFAB CRC TOPCOAT




BCT Pressure Test Tomorrow




BCT Pressure Test Tomorrow

Nothing Tomorrow


SUBFAB BUILDOUT MOD 2



























_			-	_			_	-	_	_			_				_						-									_				-			S	iding -	- East	t FAB	- PSS	S
				1																									1					В	LOW	DOW	/N 309	%	-					
E	iL 8	зк в	SJ L	зн в	3G	BF	BE	BD	E	3C	вв	BA	1	z i	Y	AX	AW	A	v	AU	AT	AS	AB	AQ		P A	N /	M	AL	AK	AJ	AB		AG	AF	AE	AD	1	AC	AB	AA	тс	тв	TA
751/752		741	7417742		731/732			721772		.17722			7	11/712	0.1 10			551/552			541/542			5317		532	532		52	521/522			51		512		E	501/502	901/902		12			
24	24	24	24	24	24	24	. 2	4	24	24	24		24	24	24	2		24	24	24	24	2	4	24	24	24	24	24	24	17		17	17	24	2		24	24	24	24	28	28		
2	12	12	12	12	12	12	1	2	12	17	17		18	17	18	1	2	12	7	7	7	2	4	24	24	18	18	18	18	17		17	17	24		4	24	24	24		28		26	Inst
2	50%	50%	50%	50%	50%	507	s 50	2	50%	71%	717		75%	71%	75%	50	24	50%	29%	29%	29%	10	0%	100%	100%	75%	75%	75%	75%	100%	1	00%	100%	100	10	0%	100%	100%	##	100%	100%	100%	93%	
0		0	0	0										0	0		·	0								0	0	0						-										
0	ō	0	0	0	0	0			Ō	0	0		0	0	0			0	0	0	0		1	1	1	0	0	0	0	1		1	1	1		1	1	1			1	1	1	
0	0		0	0	. 0			2		. 0	0		. 0	0				0	0		0		1			. 0	0					1	1			1			·····				1	
0	0		0		0								0	0								•••••					0			·····					•••••								A	1-1-
0	0	0	0	0	0	0)	0	0	0		1	0	1			0	0	0	0		1	1	1	1	1	1	1	1		1	1	1		1	1	1		1	1	1	1	4
0				0													2						1											1		! .								
0	0	0	0		0			;						· · · · · · · · · · · · · · · · · · ·		· · · · · ·			0							· · · · · · · · ·						···		1	•••••				1 177				1-1-1-1-1	4·1-
0	0	0	0	0	0	0			0	1	1		1	1	1			0	0	0	0		1	1	1	1	1	1	1	1		1	1	11			1	1		1	1	1	1	
0	0	0	0	0	0	0	0		0	1	1		1	1	1			0	0	0	0		1	1	1	1	1	1	1	1		1	1				1	1			1	1	1	3
	•••••									· · · · · ·				· • • • • • • •		••••			· · · · · · ·							· • • • • • • •					•								e de la compañía de la	1	····	· • • • • • • • • • • • • • • • • • • •		A
i	1	1	1	1	1				1	1	· · · · · · i		1	1	1			1	0	0	0		i	1		1	1	1	1	1		1	1				1	1		1	1	1	1.1.1	A.
1											····									0			1							1									····-	·····				
	1 1	1	1	1	1	1			1	1	1		1	1	1			1	1	1	1	-	1	1	1	1	1	1	1					1		1	1	1			1	1	1	+ + *
1	1	1	1	1	1	1			1	1	1		1	1	1			1	1	1	1		1	1	1	1	1	1	1					1			1	1		1	1	1	1	
ļ														· · · · · · ·																				-					·····				A	
÷		1	····	- i	····					- i					1										1	+++++++	· · · · · · · · · · · · · · · · · · ·											····					1-	
1		1		1	1	1			1	1	1		1.	1	1			1		1	1		1	1	1	1.1	1	1	1								1	1		1	1	1	1	ž
1	<u>t</u>	line		1							L												1	1	1		1	1	1										l.i.	l1			4	G
-	-		1				-							-							-	-							-			-									1	1	1	
																																									1	1	0	1


Siding - West FAB - JYG																																									
	Sidir	ng -	We	st FA	AB - J	YG	_			_		_				_	_	_			_		-	_		_		_			_	_		_	[_	· · · · · · · · ·
							BLOWDOWN 30%					_			1																										
	TA	TB	то	A	e e	в	AC	AD		AE	AF	AG	At	4	al la	AK	AL /	m	NN I	AP	AQ	AB	s	AT A			AW A	AX	AY	AZ	BA	BB	BC	BD	BE	BF	BG	вн	BJ P	3к В	L CA
		1001	1001/1002 601/602		601/602			611 / 612				62	1/622			631	/632			641/642			651/652			811		812		821/822			87	631/832			841	/ 842		851/852	
Tatal	28	T	28	28	15	18	31	1	31	31	31	1	31	31	31	31	30	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31	31
Installed	21		24	12	15	18	31	1	31	31	31		31	31	31	31	29	25	24	22	29	23	15	14	14	14	14	14	14	14	10	10	14	14	14	14	14	7	14	14	14
×	75%		86%	43%	100%	100%	100		100%	100%			100%	100%	100%	100%	97%	\$1%	77%	71×	94%	74%	48%	45%	45%	45%	45%	45%	45%	45%	32%	32%	45%	45%	45%	45%	45%	23%	45%	45%	45%
8		· + · · · ·																								· · · · · ·															
5RA	0		0	0	1	1			· · · ·	1	1		1	1	1.1	1		0	0				0	0	0	0	0	0	0	0	0	0	0	0	0	0		0	0	0	0
2			·····	····														····							0	····			0									·····			<u>0</u>
-						10 - 10 - 10				1			1	1																				0							
4DA		•••••		0							· · · · · ·				· · · · · · · · ·					0				·····		0		·····	0					0	0		0		·····		0
3																													0												
-				0	1 :	- 1 -										1								0	0	0	0	0	0	0	0				0			0			
3FK						nk				1														0		0		0						0	0						
3716	1		1	0		111	1		1	1	1		1	1	1		1	11	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0		0	0	0	0	0	0
																1																									
S surres			····	0						1				1	tri t			111			1	· · · · · · · · · ·	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3FA	1		1	1					1	1			1	1			1	1	1	1	1	1	1	0	0	0	0	0	0	0	0		0	0	0	0	0	0	0	0	0
				1						1				1			- i i					i i i					1				0	0						0			· · · · · · · · · · · · · · · · · · ·
														·····																											· · · · · · · · · · · · · · · · · · ·
			i li	i	l i l	i i			. i 1	1			. i	i i		1.1	111	1 1 1	1		. i i	i i i				11	1	i i	1	i i i		i i i	1			i i	i i i	0			
														· · · ·												·															· · · · · ·
2SA SF			1	1	1	1			1 1	1			1	1	1	i	1	1	1	1	1	i i	1	1	1	1	1	i i	1	1	1	1	1			1	1			1	· · · · ·
				1		1					· · · · · ·		1	1																											·
3	1		1	1	1	1			1	1	1		1	1		1		1.1	1		1	1	1		1	1.1	1	1			1	1	1	1	1	1	1		1.1.1		1
÷																																				1					· · · · · · · · · · · · · · · · · · ·
UL						- 4	1		1	- 1 6	1		1	1	1	1	1	1	1	1	1	1	3	1	4	1	1	1		1	1	1	4	1	1	1	1	1			1









PSSS.1






500T Build for PSSS 06/11-08/11








WJG 01J, 02J LIFT 2 & 3








WJG 03J, 04J, 05J LIFT 2 & 3







Walk Path Reroute (When Required)







MAH101-7/8-00 SET: TBD




4J COMPLETELY CLOSED 5J CLOSED DURING HOIST





WJG UTILITY LEVEL BUILD OUT








CUB 1


242

262



шŧ

HOFFMAN CONSTRUCTION COMPANY $|\Delta|$ Sparrow 📼 🌉 CUB 1 – Refrigerant Loading **CUB 1 COORDINATION MAP** В С D Έ (\mathbf{H}) R S F G M N P А Κ Q J NOTES: 1. REFRIGERANT DETECTION SYSTEM IS LIVE. 2. IF ANY ALARM IS SOUNDED - ALL WORKERS MUST EVACUATE THE BUILDING. HORNS AND STROBES WILL SOUND AND INDICATE A GAS LEAK. 3. EVACUATION LOCATION TO BE IN NORTH YARD OF CUB 1. UNTIL AREA IS SAFE TO RETURN








CUB 1 – EXTERIOR/ROOF Set Stairs 13,14,15.16 WW46-47 Set Stairs 8,9,10,11,12 WW43-45 WASTE TESTING ONGOING CHEMO SCAFFOLD WASTE TESTING MEP HOOKUP OCT ONGOING 14TH-20TH CRANE KEEP AREA CLEAR Set Stairs 17,18 WW48 BCT AHU PLATFORMS ONGOING FINAL CRC TMXW 13/10-23/10 SITE TEAM CIVIL WORK E-HOUSE E-HOUSE WASTE TESTING ONGOING TMXW PLATFORM PLATFORM ONGOING ONGOING WASTE TESTING **ONGOING NH4W** SITE TEAM IA/PA EARLY RUN NALCO EER WW 44 **ROOF WATER** CT START UP WW42 TESTING Excavate FRP CT13/15 COR CLOSEOUT FOR 17/19 Ramp 3, Stair 20 WW45-46 СТВ SITE TEAM CIVIL WORK EER RESTRICTED ACCESS AT FUEL **Revised WW 44 OIL TANK**




CUB 2








CUB 2 – EXTERIOR/ROOF







CUB 2 – Crane Logistics











T34 - dismanteling 1st level platform monday 11/11/2024









Road Demo, ading & Pavin

oncrete

Trench Drains and Paving

Daily Coordination Meeting

Ramp Concrete BSGS Light Poles

> Gas Dock Concrete

LSS install

Site Logistics North





Daily Coordination Meeting

Site Logistics South







Hot work and fire prevention.

We had two fire incidents in the past week, so it is important to refresh the procedures on this matter.

First, make sure to check and inspect the area, the task, and the team before approving the work.

Afterward, it is important to remember that when working in an area where there is a risk of sparks falling between levels, ensure that the area where the sparks may land is also safe and protected against fire.

In the event of a fire, immediately contact Hoffman personnel to report the incident.

Daily Coordination Meeting

