













# HOFFMAN CONSTRUCTION COMPANY UTILITY LEVEL P.Test









#### **BELFOR**

TTNE - Corridor + Toilets + Break R
Stairs 7.3
Wafer scrap
TTNW - Toilets + Break R
SCR 2W
Exit pass 3W


Ongoing
LSS TTNW + TTNE
BCR 1E
CHEN STAGING
LSS 2W
Chem stagging
BACKING
BCR 1E+1W - Pending funding

LSS's

MEP+Elctrical
Ready for re-install
FMS A 1E
FMS B 1W
Fire Risers 1W
BCC













#### SUT 38.1 LEVEL









SUT 38.2 LEVEL




### SUBFAB BUILDOUT MOD 1




### **SUBFAB CRC TOPCOAT**




## SUBFAB CRC TOPCOAT






### **SUBFAB BUILDOUT MOD 2**































#### Clean Room Wall Of Shame

Elram


Megason


**Elram** 



















	Siding - East FAB - PSSS
	BLOWDOWN 30%
	[A] St. [M] 60 [M] 10 [
	24 24 24 24 24 24 24 24 24 24 24 24 24 2
CB-59A-ROOF - 172166.8	
EB-40.6-EQ.0-EOC - 167798-0	
EB-3F6-FAB CEUING 16"-1" - 182,337.0	
EH-3FA-FAB - 156,825.2	
PANEL START - 150, SHEDIN	
(8-25A SUBFAB - 149,433.8 1YC - TOOL-DOCK - 347,700.0	
PANEL START - 143,947.4	9555 1377 126 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0

	Sidir	ng - V	Nest	FAB	- JY	G																																									
	BLOWDOWN 30%																																														
	TA.	TB 1001 /	TC 1002	AA	AB 601 / 60	12	vC	AD	AL 611/6	A	AF AG			AH AJ 621 / 622		AK	AL	631 /	622	AN	AD	AQ	11/642	R	AS	AT 651 / 6	AU.	AV	٨	W P11	/812	AY	AZ	8A 821/	88	вс	е		BE 11 / 832	BF	BG	,	BH	BJ 11/842	BK	BL.	CA 1 / 852
Total Installed %	28 11 39%	28 14			15 12 80%	18 18 100%	31 31 100%	3	11	31 31 100%	31 31 100%	3 100		31 31 100%	31 31 100%	31 31 1009		30 29 97%	31 23 74%	31 13 42%	3 1 55	-	31 17 55%	31 14 45%	31 6 19%	31 6 195		91 6 9%	31 14 45%	31 14 45%	31 14 45%	31 14 45%	31 14 45%	31 6 199		31 6 19%	31 14 45%	31 14 45%	31 6 19%		31 4 13%	31 4 13%	31 5 16%	31 5 16%	31 0 0%		31 0
SRA	0	0		0			T.				1			- [-]					0	0			0	0				0	0	0				0		0	0	0	0		0		0	0			0
4DA	0 0 0 0	0 0		0	4														0 0	0	000		0	0 0	0	0 0		0	0 0	0 0 0	0	0 0 0	0 0	0 0		0 0	0 0 0	0 0 0 0	0 0		0 0	0 0	0 0 0	0 0	0 0		0
3FK	0 0 0	0 0		0	Lir	٦k				1					1				0	0			0	0 0	0	0 0		0	0 0	0 0 0	0	0 0 0	0	0 0 0 0		0 0 0	0 0 0	0 0 0 0	0 0		0 0 0	0 0	0 0 0	0 0	0 0		0
3FA	0 0 0 0	0		0			1			1										0			0	0 0	0 0	0 0		0	0 0	0 0 0 0	0 0	0 0 0	0 0 0	0 0 0 0		0 0 0	0 0 0	0 0 0 0	0 0		0 0 0 0	0	0 0 0	0 0 0	0 0		0 0
2SA SI																									0 0 0 0	0 0 0 0 0 0		0 0 0 0 0						0 0 0 0 0		0 0 0 0 0 0			0 0 0 0 0 0 0		0 0 0 0 0	0 0 0 0	0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0		0 0 0 0 0
u										1																											1				0	0	0	0	0 0		0 0 0

 PSSS.1



### PSSS.2



## PSSS 4P VFD Set

Hoist VFD – 24/09











































































**Site Logistics**Underground Utilities


### **ALL UNDERGROUND UTILITIES ARE LIVE!**

- Temp water
- Temp power (22kv)
- Storm
- Sewer
- Domestic Water
- Fire Protection Water (Intel fire pumps and alarms!)

Systems are connected to buildings and cannot be damaged or used without HCC approval.












Site Logistics


North IQ Staging Access







Site Logistics







### Barricades

- We are not seeing the improvement with barricades needed as work areas become more congested and more and more activities are taking place on site.
- Please talk with all of your crews about the following:
- All barricades must be completely enclosed, have a gate, and have signage defining the hazard and the contact person.
- Red barricades are needed for life threatening hazards.
- Barricades are not to stay in place after the hazard is no longer present, meaning at the end of the shift if we are leaving a barricade up because we are also leaving a hazard, we need to communicate with the HCC superintendent for that area.
- Barricades must be maintained, this sometimes requires fixing them throughout the shift.
- Please, make this a priority with your team. Barricades are vital communication tools on our site. Currently, we aren't communicating well.

