

14:00 Sign In






General Topics:

- Status update on companies allowed to work.
- Requirements for MEWP release complete & repair deficiencies found in audits, manufacturer sign-off, HCC sign-off, Intel sign-off, final approval.

HOFFMAN CONSTRUCTION COMPANY UTILITY LEVEL MOD1










SUT 38.1 LEVEL








SUT 38.2 LEVEL





IK1 Ibrahim Krinawi, 3/5/2025





SUT 38.1 LEVEL







































SUT 1 IS NOT STORAGE AREA

NEED CLEANUP& EVACUATE ALL MATERIALS & TOOLBOXES


TILL EOW 10TH MUST EVACUATE ALL MATERIALS, OTHER WISE ON 13TH HCC WILL THROGHT UNAPPROVED STUFF TO DUMSTER!!

EVERY TOOLSBOX OR MATERIALS MUST BE APPROVED - TALK TO HCC SUP- IBRAHIM


SUBFAB BUILDOUT MOD 1




W&W Elev' Crane Beams




SUBFAB CRC TOPCOAT




SUBFAB BUILDOUT MOD 2

































輸



PSSS.2



BGY GN2 Purging

14th- 17th Intermittent noise

18th-20th continuous noise BGY Closed








$\underline{WJG-UL}$

	* Chemo - performing passivation on UPN 111 (UL + lift 2) and working on permanent support for hydronic pipes		
--	--	--	--




211 11

回日前



WJG - Lift 2

* Chemo - started restoration on UPN 113	* Carmel Bidud - fixing planking and removing handrails behind 4J and 5J VFD.	* Chemo - performing passivation on UPN 111 (UL + lift 2) * SK - installing drains behind 4J and 5J VFD



(AE) (AF) (AM) (AN) (AP) (AQ) (AR) (AS) AU (BC) (BD) (BE) (BF) (BG) (BH) (BJ) (BK) (BL) (CA) (AD) (AG) AH (AT (AV) (AW) (AX) BB AJ (AK) AL (AY) AZ BA

The second secon		BDC STAR6 EB0Q-ST0		STAR		n di		USTAIR 12	[28,-0]
								0 7315	1 24-01
		JUNGLE GYM		00	0.0	0 0 0		5:82	01 1 [24'-0 14630 [48'-01
			帝帝				AA.		

		* SN - handrails installation and supports	

WJG - Lift 3






Crane logistics


Crane: 750 ton crane moved south of RCTO Tuesday 15/04/25






CUB1 Ops Ready April 29








CUB 2- Load in & H&T
















Site Logistics North







Site Logistics North







Site Logistics South








MAMAD Locations








Daily Coordination Meeting WATER BOTTLE FILLING STATIONS









BACK TO WORK REQUIREMENTS

.....

B.V.S

Carmel Bidud LTD (FAB + PSSS) CHEMO AHARON LTD (FAB) D&P Clean Room Ltd DVIR.IE LTD ELECTROSAFE LTD EL-MORE ELECTRIC ELRAM PROJECT LTD ES Entry Systems LTD ETC Systems LTD Gamida Lesico LTD Newco - Tec LTD Rolling Plains Constriction Inc Sami Najami Engineering & Project LTD SIG Industrial LTD SK ENGINEERING & PROJECT (CUB) Talad T.S LTD TM TEAM LTD TM TEAM LTD- Job service Yerushalmi Water Cooling Tower LTD Olizki Infrastructures LTD s-k Makam Engineering

Afcon Contracting Services	
Avi Cranes	
E.L Fireproof LTD	
Electra Elevator	
GLOBUS WORLDWIDE LOGISTICS	
HB	
HYG STEEL 1990 LTD	
JACOBS	
LVTH	
MEGASON ELECTRONIC & CONTROL 1987 LTD)
ORIAYN ADVANCED TECNOLOGY SYSTEMS, I	LTD
QA- AMTS, Q+,DPS	
Rescue 1	
Sela Industrial Maintenance 2006LTD	
Siemens Industrial LTD	
Skyline Cranes& Technologies	
Stage Design Ltd	
TEAM3 LTD	
TZUR ESH PROJECTS LTD	



BACK TO WORK REQUIREMENTS

1. All workers must go through the training that was done at 7am on the Mass Safety Meeting.

 Perform audits on all equipment onsite (forklifts, MEWP, cranes, etc.). Upload MEWP checklists.

Update all the RAMS that include MEWP.
Training on company policies for loaning equipment to others. Make sure each MEWP has a company name on it.

5. Training on new site policy of MEWP use Have list of all approved operators and spotters for each MEWP. A printed copy has to be on each MEWP.

6. Submit all training records.



